



Safety Gate: Rapid Alert System for dangerous non-food products

| Alert number | A12/0074/16 |
|---|---|
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Honda |
| Name | NSS125 (FORZA) |
| Type / number of model | NSS125ADF (E, ED, EDF, EDHN, EDIT, EDPO, EDSP, EDSW) and NSS125DF (ED, EDPO); EU Type Approval number: e4*2002/24*3136*00. |
| Batch number / Barcode | Year model: 2015. Production period: from 09th March to 15th May 2015 |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle |
| Country of origin | Italy |
| Alert submitted by | Portugal |
| Risk type | Injuries |
| Risk | The rubber seal of the coupler between the main wire harness and the engine sub-harness may have been damaged during assembly. As a result, water could enter the coupler. If water enters the coupler, it could, in the worst case, cause the engine to stall. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | The Netherlands, Germany, Estonia, Poland, Croatia, Slovakia, Finland |
| Images | No pictures are available |