

Safety Gate: Rapid Alert System for dangerous non-food products

| Alert number | A12/00321/20 |
|---------------------------------------|---|
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Suzuki |
| Name | Address |
| Type / number of model | Type-approval number: e4*2002/24*3114*00 |
| Company recall code | C82 |
| Production dates | The affected vehicles were manufactured between October 2014 and May 2019. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle under Suzuki recall code: C82. |
| Country of origin | Indonesia |
| Alert submitted by | Belgium |
| Risk type | Injuries |
| Technical defect | Improper plating material was used on the movable contact terminals of the horn and brake switches, which can lead to corrosion of the contact surfaces. As a result, the horn will not work properly and the engine may fail to start, increasing the risk of an accident. / |
| Risk | |
| Measures adopted by notifying country | Recall of the product from end users |
| Images | No pictures are available |
| | |