



Safety Gate: Rapid Alert System for dangerous non-food products

8
A12/0632/15
Motor vehicles
Products with serious risks
Consumer
Motorcycle
Honda
CBR1000RR SP
Type: SC59; EC type-approval: E4*2002/24*1726
Vehicles manufactured in 2014 and 2015 are concerned.
77000000 - Automotive
Motorcycle.
Japan
Germany
Injuries
Due to insufficient tightening, the connecting rod nut for the shock absorber may become detached and thus impair the shock-absorbing effect. In the worst-case scenario the rider may lose control over the motorcycle.
Recall of the product from end users
The Netherlands, Croatia, Sweden, United Kingdom, Ireland, Denmark, France, Malta, Greece, Portugal, Hungary
No pictures are available