



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|-----------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Alert number | A12/0916/15 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycles |
| Brand | Honda |
| Name | CB / CBF / CBR / CRF / CTX / FES / FJ / NC / NSS / NT / SH / ST / VFR / VT / XL |
| Type / number of model | CB1300SAA, CB500FAE, CB500XAE, CB650FAE, CBF1000FAC, CBF1000FTC, CBR125RD, CBR300RAF, CBR500RAE, CBR600RAD, CBR650FAE, CRF250LD, CRF250ME, CTX700DE, CTX700NDE, FES125AC, FJS600A7, NC700SDE, NC700XDE, NC750DE, NC750JF, NC750SAE, NC750XAE, NSS300AD, NT700VAB, SH300AE, ST1300AE, VFR800A9, VT750C2BE, VT750CSE and XL125VB. |
| Batch number / Barcode | Affected motorcycles are those manufactured between September 2013 and June 2015. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycles. |
| Country of origin | Japan |
| Alert submitted by | Portugal |
| Risk type | Fire, Injuries |
| Risk | A manufacturing problem with the starter relay switch could 1) affect the electrical system causing the engine to stall while riding leading to a road accident; or 2) cause the starter relay switch to catch fire. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | The Netherlands, Slovenia, Estonia, Slovakia, Ireland, Croatia, France, Sweden, Greece, Hungary |
| Images | No pictures are available |