

Safety Gate: Rapid Alert System for dangerous non-food products

| Alert number | A12/0792/16 |
|---|---|
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Honda |
| Name | GL1800 |
| Type / number of model | 1HFSC47N18A700131-1HFSC47N58A701640, 1HFSC47N57A6000001-1HFSC47N77A602056, 1HFSC47N57A600497-1HFSC47N87A601546, 1HFSC47NX8A600001-1HFSC47P97A600780, 1HFSC47NX8A700001-1HFSC47NX8A701780, 1HFSC47P68A700031-1HFSC47PX8A701120, GL1800, Type-approval number: e4*92/61*0107*05 |
| Batch number / Barcode | The affected vehicles are produced between 25 May 2006 and 5 August 2008. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle. |
| Country of origin | United States |
| Alert submitted by | United Kingdom |
| Risk type | Injuries |
| Risk | Airbag inflators may degrade over time due to heat and moisture. The inflator body may rupture while activating and metal fragments may pass through the cushion material causing injuries to the rider. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Cyprus, Denmark, Estonia, Finland, Germany, Greece, Ireland, Portugal, Slovakia, Slovenia, Sweden, The Netherlands |
| Images | No pictures are available |