



Safety Gate: Rapid Alert System for dangerous non-food products

| Alert number  | A12/01180/20   |
|---|--|
|   |  |
| Category  | Motor vehicles   |
| Type of alert                                       | Products with serious risks  |
| Product user  | Consumer   |
| Product   | Motorcycle   |
| Brand   | Triumph  |
| Name  | Street Scrambler, Street Twin  |
| Type / number of model                              | e5*168/2013*00009 e5*168/2013*00010<br>e5*168/2013*00011 e5*168/2013*00012   |
| Company recall code                                 | SRAN584  |
| Production dates                                    | The affected vehicles were manufactured between 9 August 2018 and 23 July 2020.  |
| OECD Portal Category                                | 77000000 - Automotive  |
| Description   | Motorcycle   |
| Country of origin                                   | United Kingdom   |
| Alert submitted by                                  | United Kingdom   |
| Counterfeit *                                       | UNKNOWN  |
| Risk type   | Injuries   |
| Technical defect                                    | A wiring harness may be misrouted and can become damaged<br>by coming into contact with the lower lug on the main frame<br>headstock. This can result in an engine stall, increasing the<br>risk of an accident. / |
| Risk  |  |
| Measures adopted by notifying country               | Recall of the product from end users   |
| Products were found and measures were taken also in | Germany, Poland  |
| Images  | No pictures are available  |