

Safety Gate: Rapid Alert System for dangerous non-food products

| Alert number | A12/1727/19 |
|---------------------------------------|---|
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Three-wheel motorcycle |
| Brand | Polaris |
| Name | Slingshot S / SL / SLR / GT |
| Type / number of model | Model year 2015 and 2019 |
| Batch number / Barcode | The affected vehicles were manufactured between 15/05/2014 and 25/04/2016. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Three-wheel motorcycle. |
| Country of origin | United States |
| Alert submitted by | United Kingdom |
| Risk type | Injuries |
| Technical defect | Under certain conditions, the capability of the battery fuse block terminals might be exceeded by the actual electrical current requirements. |
| Risk | Consequently, the terminal could be damaged leading to a loss of forward and rear lighting, instrument cluster or power steering assist, increasing the risk of accident. |
| Measures adopted by notifying country | Recall of the product from end users |
| Images | No pictures are available |