



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1179/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Kawasaki
Name	VN1700
Type / number of model	VN1700 Voyager and VN1700 Voyager Custom
Batch number / Barcode	VN1700B9/BA/BB/BC/BD/BE/BF: KBVNT70ABA000027 to JKBNVT70ABA015079 , VN1700KB/KC/KD/KE/KF: JKBNVT70JKA000022 to JKBNVT70JKA010132
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Japan
Alert submitted by	Greece
Risk type	Injuries
Risk	The insulation on the ignition switch harness may rub on the underside of the fuel tank. This can lead to an electrical short circuit which may cause the engine to stall.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Hungary, Portugal, Slovakia, Slovenia, Sweden, United Kingdom
Images	No pictures are available