
Alert number **[A12/00555/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The valve guides may have quality issues that could lead to excessive wear of the engine components. Consequently, this excessive wear can lead to engine failure, which may increase the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Ducati Multistrada V4S, model year: 2021**

Brand **Ducati**

Name **Multistrada V4S**

EC-type approval/model **e9*168/2013*11661*00**

Production dates **Model Year: 2021**

Company recall code **CR208**

Weekly report number **Report-2021-16**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**