



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0094/16
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycles
Brand	BMW
Name	C 600 Sport / C 650 GT
Type / number of model	Types: K18, K19 EC type approval: e1*2002/24*0552
Batch number / Barcode	Affected vehicles manufactured between 9.2.2011 and 15.7.2015.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle.
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Risk	The positioning of the chafer can cause damage to the front brake hose and lead to a loss of brake fluid. This can reduce brake performance and could lead to accidents.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Finland, Greece, Ireland, Malta, Norway, Portugal, Slovakia, Slovenia, Spain, Sweden, The Netherlands, United Kingdom
Images	No pictures are available