



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0221/16
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycles
Brand	SUZUKI
Name	DL650 and AN650
Type / number of model	Models DL650_A_L4-L6 and AN650_ZL3-ZL4
Batch number / Barcode	Model years of the affected motorcycles are 2012-2014
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Japan
Alert submitted by	Greece
Risk type	Injuries
Risk	The engine tappets and cams can wear, increasing the tappet clearances. If the tappet clearance becomes large, it can, in the worst case, cause the engine to stall.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Germany, Hungary, Norway, Slovakia, The Netherlands, United Kingdom
Images	No pictures are available