



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|--|
| Alert number | A12/0491/16 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Kawasaki |
| Name | ZX100SG |
| Type / number of model | Ninja ZX10R 2016 |
| Batch number / Barcode | Unknown |
| OECD Portal Category | 77000000 - Automotive |
| Description | 1000-cc motorcycle |
| Country of origin | Japan |
| Alert submitted by | Spain |
| Risk type | Injuries |
| Risk | The steering damper bracket bolts may have been excessively tightened during assembly. This could cause them to break and interfere with the steering. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Bulgaria, Denmark, Finland, Slovakia, Slovenia, Sweden, The Netherlands, United Kingdom |
| Images | No pictures are available |