



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0679/16
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Honda
Name	SH
Type / number of model	EU Type-approval numbers: e4*2002/24*2896*00, e4*2002/24*2897*00, e4*2002/24*2896*01 and e4*2002/24*2897*01. , Model years 2013 and 2014, Models: SH125 and SH150
Batch number / Barcode	Production period: from 10th July 2012 to 31st January 2015.
OECD Portal Category	77000000 - Automotive
Description	Motorcycles.
Country of origin	Italy
Alert submitted by	Portugal
Risk type	Injuries
Risk	The surface of the resin inlet cover in the fuel pump may deform, reducing the clearance between the inlet cover and the fuel pump's impeller. Consequently, the two components may interfere with each other. As a result, the impeller locks, stopping fuel flow to the engine which may cause the engine to suddenly stall.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Estonia, Finland, Germany, Greece, Poland, Slovakia, Slovenia, Sweden, The Netherlands, United Kingdom
Images	No pictures are available