



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0701/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Yamaha
Name	DM01 - DM04
Type / number of model	EC type-approval: e13*2002/24*0565, e13*92/61*0085; sales description: XT660R, XT660X, XT660Z, XT660ZA
Batch number / Barcode	N/A
OECD Portal Category	77000000 - Automotive
Description	Motorcycles manufactured in 2014 and 2015 are affected.
Country of origin	France
Alert submitted by	Germany
Risk type	Injuries
Risk	Some motorcycles may be affected by damage to the gearbox, due to an incorrectly drilled banjo bolt in the gearbox's oil supply hose. This may result in an inadequate oil supply to the gearbox and, in the worst-case scenario, the gear shafts may jam completely, causing the rear wheel to block, possibly resulting in loss of control of the vehicle.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	The Netherlands, Sweden, Slovakia, Croatia, Denmark, United Kingdom, Greece, Portugal, Norway
Images	No pictures are available