



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0852/16
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	SUZUKI
Name	Address
Type / number of model	EC-type approval: e4*2002/24*3114*00; Type: UK 110; Code DE
Batch number / Barcode	The vehicles affected have been manufactured between October 2014 and March 2016.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle.
Country of origin	Indonesia
Alert submitted by	Spain
Risk type	Fire, Injuries
Risk	A fixing nut of the starting pedal could become loose while driving, resulting in the engine cutting out. Moreover, a screw could become loose in the air filter, which could become trapped in the throttle valve, blocking acceleration so that the motorcycle cannot reduce speed. In some units of the product the fuel hose connector is not properly connected, which could cause a fuel leak.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Finland, Germany, Greece, Ireland, Norway, Slovakia, Sweden, The Netherlands
Images	No pictures are available