



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0070/19
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Motorcycle
Brand	Ducati
Name	Panigale V4, Panigale V4 S, Panigale V4 Speciale
Type / number of model	Unknown
Batch number / Barcode	
OECD Portal Category	77000000 - Automotive
Description	Motorcycle.
Country of origin	Italy
Alert submitted by	Italy
Risk type	Injuries
Technical defect	A crack may occur at the level of the outlet pipe of the oil cooler.
Risk	As a consequence, oil may leak leading to an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	The Netherlands
Images	No pictures are available