



Safety Gate: Rapid Alert System for dangerous non-food products

| Alert number | A12/0086/16 |
|---|---|
| Alert humber | A12/0086/16 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycles |
| Brand | KAWASAKI |
| Name | W800 |
| Type / number of model | Models EJ800AB, EJ800AC, EJ800AD, EJ800AE, EJ800AF, EJ800AG |
| Batch number / Barcode | The recall affects 2011-2016 models with serial numbers: Models EJ800AB, EJ800AC, EJ800AD: from JKBEJ800AAA000044 to JKBEJ800AAA015854 Models EJ800AD, EJ800AE, EJ800AF, EJ800AG: from JKBEJ800AAA015861 to JKBEJ800AAA026549 |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle |
| Country of origin | Japan |
| Alert submitted by | Greece |
| Risk type | Injuries |
| Risk | A wiring harness under the fuel tank may be damaged from contact with the frame edge.This can lead to a short circuit and possible engine stall. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Bulgaria, Croatia, Denmark, Finland, Portugal, Slovakia, Slovenia, Sweden, The Netherlands |
| Images | No pictures are available |