



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1552/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Suzuki
Name	GSX-R1000R/RZ
Type / number of model	Type-approval numbers: e4*168/2013*00052*01, e4*168/2013*00052*02;; model codes: GSX-R1000RAL7, GSX-R1000RZAL7, GSX-R1000RAL8, GSX-R1000RZAL8
Batch number / Barcode	The affected vehicles were manufactured between 10 March 2017 and 7 January 2019.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle under Suzuki recall code: 97EZ.
Country of origin	Japan
Alert submitted by	Poland
Risk type	Injuries
Technical defect	Due to improper communication control program, unnecessary error signals are transferred between the inertial sensor and ABS unit when the battery voltage is too low.
Risk	As a result, the ABS function may not work, increasing the risk of an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Finland, Ireland, Sweden
Images	No pictures are available