



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0525/15
Alert humber	A12/0525/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Polaris
Name	Scout and International Scout
Type / number of model	56KMSA000F3000194 - 56KMSA00XF3100366
Batch number / Barcode	Build dates: 12/5/14 - 13/2/15.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle.
Country of origin	United States
Alert submitted by	United Kingdom
Risk type	Injuries
Risk	The piston retaining ring, located in the rear brake master cylinder, may not fully seat into the machined groove in the master cylinder bore. If this occurs, loss of fluid pressure to the rear caliper could cause lack of braking control.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Germany, The Netherlands, Greece
Images	No pictures are available