



Safety Gate: Rapid Alert System for dangerous non-food products

	· · · · · · · · · · · -
Alert number	A12/1201/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Yamaha
Name	YZF-R1, YZF-R1M
Type / number of model	Type: RN32 EC-type approval: e1*2007/24*0740
Batch number / Barcode	The vehicles concerned were manufactured in 2015.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Japan
Alert submitted by	Germany
Risk type	Fire
Risk	Because of possible damage to an O-ring, fitted poorly when the engine was assembled, motor oil can leak from one of the oil pipes. As the oil pipe is located outside close to the engine, at the level of the exhaust manifold, the leaking oil could drop onto the hot exhaust manifold while the motorcycle is being driven and catch fire.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	France, The Netherlands, Croatia, Sweden, Ireland, Slovenia, Slovakia, Denmark, Bulgaria, United Kingdom, Portugal, Greece
Images	No pictures are available