



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0519/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Suzuki
Name	Address
Type / number of model	EC type-approvals: e4*2002/24*3114*00-01 e4*168/2013*00076*00; Types: DE, WDE0 e4*168/2013*00076*00 Typen: DE, WDE0
Batch number / Barcode	The vehicles affected were produced between May 2015 and March 2018.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle. Company recall code: 97EL.
Country of origin	Indonesia
Alert submitted by	Germany
Risk type	Injuries
Technical defect	Owing to a production fault, the angle of the generator rotor installation on the crankshaft may not be adequate.
Risk	This may cause damage to the crankshaft and subsequently lead to engine failure and to an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Poland
Images	No pictures are available