



Safety Gate: Rapid Alert System for dangerous non-food products

|   | 440/00005/00   |
|---|--|
| Alert number  | A12/00085/20   |
| Category  | Motor vehicles   |
| Type of alert                                       | Products with serious risks  |
| Product user  | Consumer   |
| Product   | Motorcycle   |
| Brand   | Ducati   |
| Name  | Multistrada 1260   |
| Type / number of model                              | Type-approval number: e3*168/2013*00010, Type: AC  |
| Batch number / Barcode                              | CR184  |
| OECD Portal Category                                | 77000000 - Automotive  |
| Description   | Motorcycle under Ducati recall code: CR184.  |
| Country of origin                                   | Italy  |
| Alert submitted by                                  | Germany  |
| Risk type   | Injuries   |
| Technical defect                                    | The sidestand may break due to defective welding. As a result, the motorcycle can inadvertently fall, increasing the risk of injuries.<br> |
| Risk  |  |
| Measures adopted by notifying country               | Recall of the product from end users   |
| Products were found and measures were taken also in | Poland   |
| Images  | No pictures are available  |