



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00086/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Quadro
Name	QUADRO3
Type / number of model	
Batch number / Barcode	
OECD Portal Category	77000000 - Automotive
Description	Three-wheel motorcycle.
Country of origin	Italy
Alert submitted by	Italy
Risk type	Injuries
Technical defect	The backrest/carrier (Sissy bar) is not sufficiently strong and could break. This can lead to loss of the load, posing a risk to the following traffic. 
Risk	
Measures adopted by notifying country	Warning consumers of the risks
Images	No pictures are available